


FLIR0044.JPG

2018/01/04 22:23:07

FLIR0044.JPG

2018/01/04 22:23:07



MEASUREMENTS

°F

Spot 1	61.4
--------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.00 °F
Distance	3.28 ft
Relative humidity	50 %
Atmospheric temperature	68.00 °F
Transmission	0.94

Insulation is missing on upper portion of the wall cavity separating living room and garage.

How well are your walls insulated? Call Top Choice Home Inspections today
 330-614-0054